



User Guide



Patented

Table of Contents

1	General information.....	4
1.1	Guarantee	4
1.2	Safety instructions	4
1.3	Transport.....	5
1.4	Storage.....	5
2	Product description.....	5
3	Content, accessories and options	6
4	PAViX – HMI.....	7
4.1	Barrel configuration	7
4.2	Generation and creation of hand-setting programs	7
4.2.1	Entering family names and programs	8
4.2.2	Recording a working reference.....	8
4.2.3	Editing the program	8
4.2.4	Edition of hand-setting programs.....	9
4.2.5	Authorisation to correct hand fitting heights	9
4.3	Management of the bar code database	10
4.3.1	Bluetooth interface for HMI	10
4.3.2	Bar codes or QR code	10
4.3.3	Scanner.....	10
4.3.4	Pairing a scanner to the HIM	12
4.3.5	Bar codes <-> program link	13
4.4	Strategic management of traceability.....	14
4.5	Program import / export	15
4.5.1	Exporting.....	15
4.5.2	Importing.....	16
4.6	Software update	17
5	PAViX - staking-tool.....	18
5.1	Cleat loading / changing.....	18
5.2	Battery change and recharging	19
5.3	Battery change (CR2032)	19
5.4	PAViX LCD.....	19
5.5	Start up.....	21
5.6	Configuration of PAViX settings	21
5.6.1	Barrel configuration.....	22
5.6.2	Recording cleat references	22
5.6.3	Time/Date	23
5.6.4	Spindle reference.....	23
5.6.5	User type change.....	25
5.6.6	Buzzer.....	25
5.6.7	LED	25
5.6.8	Screen contrast.....	25
5.6.9	Sleep timer.....	26
5.6.10	Bluetooth.....	26
5.6.11	Use of a bar code reader (Bluetooth scanner)	26
5.6.12	Information	27
5.6.13	Language	28
5.6.14	Traceability.....	28
5.7	Program and data management	29
5.7.1	Access to the ADMIN menu.....	29

5.7.2	Program updates	30
5.7.3	Recovery of hand fitting results	30
5.8	Software update	32
6	Hand-setting	33
6.1	User identification	33
6.2	Selection of the hand-setting program	33
6.2.1	Manual selection	33
6.2.2	Automatic loading of the bar code program	34
6.3	Performing a hand-setting operation	35
6.3.2	Hand-setting	37
6.3.3	Hand-setting operation results	39
6.3.4	Height corrections	40
7	Exclusion of liability/guarantee	41
8	Maintenance and service	41
8.1	Cleaning of the spindle	41
8.2	Cleaning of spindle smooth bearings	42
8.3	Replacement of the backup battery (CR2032)	42
8.4	Sensor inspection	43
8.4.1	Access to the Maintenance menu	43
8.4.2	Verifying force measurement accuracy	44
8.4.3	Force calibration	46
8.4.4	Distance validation	47
9	Representation/distribution	48

Tracked Changes:

Ver.	Date	Drafted by	Changes	IHM	POT	Valid.
V3.0	10.10.2017	<u>JSA</u>	Pre-validation	V4_00	V4_00	
V3.1	24.10.2017	<u>BAP</u>	Publication of V4.0 SW	V4_00	V4_00-02	<u>RVA</u>
V3.2	01.02.2018	<u>BAP</u>	Traceability: continuous ID	V4_00	V4_00-03	

	VOH SA	GU-04-06-01
	PAViX - User Guide	Version 3.2
		Created 10.2017
		Page 4 / 48

1 General information

1.1 Guarantee

VOH SA warrants this product against any defects in manufacturing or in materials under normal conditions of use and service for a duration of two years from the date of commissioning at the client's premises. If, at any time during the guarantee period, the product is found to be defective or fails, VOH SA shall repair or replace it (at the discretion of VOH SA).

If the product is defective, please call VOH Customer Service on +41(32) 945 17 45.

The warranty shall not apply if VOH SA proves the default or failure is due to improper use of the equipment.

The product is equipped with seals of warranty. Breaking or severing these seals leads to cancellation of the warranty.



Figure 1: Seal of warranty

The scope of VOH SA's liability is limited to the repair or the replacement of the product under the terms set out above.

VOH SA SHALL NOT BE HELD LIABLE FOR ANY LOSS OR DAMAGES, INCLUDING INCIDENTAL OR CONSEQUENTIAL DAMAGES ARISING DIRECTLY OR INDIRECTLY FROM A BREACH OF THE GUARANTEE, EXPRESS OR IMPLIED, OR ANY OTHER FAILURE OF THIS PRODUCT. THIS GUARANTEE IS THE ONLY EXPRESS GUARANTEE PROVIDED BY VOH SA FOR THIS PRODUCT.

This guarantee only covers the initial buyer and is not transferable.

If you have any questions regarding the guarantee, please write to VOH SA at the following address:

VOH SA
La Praye 5a
CH-2608 Courtelary

Telephone: +41(32) 945 17 45
Fax: +41(32) 945 17 55
e-Mail: customer-service@voh.ch
Internet: <http://www.voh.ch>

1.2 Safety instructions

Warning

- Do not use the PAViX if it is damaged. Before using the PAViX, inspect its enclosure, the condition of its battery as well as its electrical connections.
- The PAViX must be used according to the manufacturer's recommendations.
- Do not use the PAViX in a dirty environment.
- The PAViX should only be used by people who have been trained to use the device.

Caution!!!

- Please read the information contained in this manual prior to using the equipment. Improper use may damage the system or lead to incorrect results.
- When not using the device for extended periods, remove the battery.
- Do not disassemble the device. The manufacturer reserves the right to replace or repair a defective component.
- Use this device at a temperature between 10°C and 40°C (140 °F).

1.3 Transport

This device is not designed for frequent transport. However, if it is necessary to move the device, take care not to expose it to shocks that could deteriorate its mechanics. Similarly, in the event of transport over long distances, use shock-protecting packaging.

1.4 Storage

The PAViX must be stored in a dry and dust-free environment. Storage temperature must be between 10°C and 40°C. It is recommended to cover the device in order to protect it from dust and moisture.

2 Product description

The PAViX is a staking-tool with smart and universal hands. It enhances operator skills while supplying, in a non-intrusive way, the technical means required for hand-setting operations. Hand-setting operations are therefore well mastered and traceability of these operations is ensured.

Set out below is the PAViX workflow:




Figure 2: PAViX workflow

3 Content, accessories and options




Figure 3: PAViX and accessories

4 PAViX – HMI

The generation, edition and management of PAViX programs is conducted via an HMI. A unique HMI screen allows for the management of an unlimited number of PAViXs.




Figure 4: HMI and connectors

4.1 Barrel configuration

The programs use a common barrel configuration. It is managed from the PAViX HMI that is then automatically transferred to the SD card when the programs are exported.




Figure 5: Barrel configuration management

In order to change the numbers of the cleats present on the barrel, simply click on the fields located around them then link a standard cleat by clicking in the list located on the right-hand side of the screen.

To “remove” a cleat, simply double-click on the corresponding field. The number then becomes ‘---’ meaning: no cleat mounted in this position of the barrel.

4.2 Generation and creation of hand-setting programs

Program management and creation is conducted via the PAViX HMI. The transfer of programs on the PAViX staking-tool is performed with an SD card.

Hand-setting programs are classified by family then by program.




Figure 6: Home screen and program management

In order to create programs, the PAViX may or may not be connected to the HMI using the supplied cable. La status of the staking-tool <-> HMI connection is displayed on the top right-hand corner of the screen.



Figure 7: Unconnected staking-tool / Connected staking-tool

4.2.1 Entering family names and programs

On the home screen, select the navigation icon then press the "+" icon in the left column.




Figure 8: Home screen with navigation icon / Home screen with "+" icon / Creating a calibre

4.2.2 Recording a working reference

It is required, for each created program, to define a height reference for the part-holder movement assembly. This reference is done using a defined cleat.

The user defines a point on the part-holder that will be used for the reference as well as the height. It is recommended to set this reference on the hour hand's hour-wheel or on the minute-wheel.

The user selects the tool position. The cleat number is automatically populated, on the basis of the information entered in the barrel configuration.

In order to compensate a potential flexion in the movement, the strength of reference "0" can be set to 5 - 20 N.



Figure 9: Selecting the parameters to record the working-program reference

4.2.3 Editing the program

Once the working reference is recorded, the user can enable the stages of the sequence required to set the hands. A program allows for the setting of up to 14 different hands. Each stage has the following settings:

- Tolerance of min and max force (mandatory)
- Stop height (mandatory)
- Barrel position (mandatory)
- Type of hands set (optional)

4.2.3.1 Programming by learning (ONLINE mode)

Height teaching is carried out with the wheel stop. The height is displayed in real-time and saved using the "SET" button. To change force, cleat no. and hand type settings, simply select the field concerned.

NOTE: To adjust the height, the position of the barrel on the staking-tool must match that of the selected operation. If the position of the barrel does not match that of the selected operation, the height is displayed in red and cannot be changed.

4.2.3.2 Programming by theoretical values (OFFLINE mode)

Height values are determined on the basis of a plan and are manually entered on the hand's detail page.

Note: All height values can be changed OFFLINE by 0.01mm increments and saved.




Figure 10: Editing the program

To enter the hand type, simply click on the corresponding field to access the page below. A hand name can have a maximum of 4 characters.



Figure 11: Entering a hand name

4.2.4 Edition of hand-setting programs

Once the programs are developed, simply double click on a program to start its edition. The edition process can be performed with or without a connected staking-tool.

4.2.5 Authorisation to correct hand fitting heights

Once the programs are created on the HMI, it is generally no longer necessary to correct hand fitting heights when using the staking-tool.

However, it is possible for the operator to authorise a temporary height correction: simply activate the “Ht correction” radio button on the Family/Program page:




Figure 12: Height correction

Use of the option to correct heights when carrying out hand fitting operations is detailed here: spindle (refer to: § 5.6.4 Spindle reference, page 23).

4.3 Management of the bar code database

4.3.1 Bluetooth interface for HMI

This optional interface allows direct communication between the scanner and the HMI. We recommend using a dedicated scanner (to use with the HMI) in order to facilitate the work (VOH Scanner 26.01001.SP.09)




Figure 13: Adapter assembly

Note:

- In order to work, the Bluetooth interface for HMI must be powered with the supplied USB power supply.
- The small white button on the “LM” module must be placed on the “DCE” side

4.3.2 Bar codes or QR code

Below can be found the minimum dimensions in order for the QR codes (ISO 18004) and bar codes (Code 128) to be readable by the PAViX Scanner:




Figure 14: Bar code and QR code dimensions




4.3.3 Scanner

The 1D/2D VOH (VOH 26.01001.SP.09) scanner is capable of scanning simple bar codes and QR codes.



Figure 15: VOH Scanner

Scanner statuses:

Status LED	Status	Comment
	Continuous	Charging (button on the ON or OFF position)
	Short flash	Press scan button
	Long flash	Scan successful
	Flashing	Not connected, discoverable

Scanning area:

When pressing the “Scan button”, the scanner projects 2 blue strips.





Figure 16: scan and blue strips


By varying the distance between the scanner and the target, it becomes possible to make both strips overlap in the centre: in order to read the code, it must be located at the intersection of the 2 strips! When reading is successful, a “bip” from the scanner can be heard.

 To facilitate the scan, start close to the bar code and gently move away until a long “bip” can be heard.

Battery life:










2 hours charging time.




2 days of operation (1 scan per minute) without having been set to “OFF” at night.

 Charging the scanner every night is recommended.

4.3.4 Pairing a scanner to the HIM

Like any other Bluetooth device, the scanner must be paired before use.

PAViX HMI screen	Comment(s)	Scanner
 <p>+ USB power supply</p>	<p>Check for the presence of the Bluetooth adapter at the back of the PAViX HMI Power it with the supplied USB power supply</p>	OFF
	<p>Click on the "DB" button to access the bar codes <-> programs linking pages</p>	OFF
	<p>Select any program. The number of bar codes already linked to the various programs is specified in brackets.</p>	ON Blue LED flashes 
	<p>By clicking on the left-hand side button, the HMI will start searching for a Bluetooth scanner</p>	ON Blue LED flashes 
	<p>The search may take up to 30 seconds.</p>	ON Blue LED flashes 
	<p>The list of detected scanners appears. The selected MAC address (1) must match the address engraved at the back of the scanner. Validate the selection (2).</p>	

 	<p>Pairing then proceeds without user action.</p>	<p>Once pairing is successful, the scanner's blue LED turns off: it is ready to be used.</p>
	<p>The scanner's connection indicator, on the top right-hand corner of the screen, then becomes green.</p>	

4.3.5 Bar codes <-> program link

The PAViX automatically calls the programs when scanning bar codes. Several bar codes may be assigned to the same program (family + program). Management is conducted via the HMI. Press the “DB” button to access then select the desired program.






Figure 17: Accessing the bar code management section

If it isn't the case, connect the staking-tool or the scanner's interface module to the HMI and then scan the bar code to be assigned to the selected program.



Figure 18: Scanning a bar code

Note: Linking the same bar code to several programs is not possible. A bar code may not contain more than 20 characters, including spaces.

To delete a bar code, press the  after selecting the bar code to delete. Confirm selection by pressing the  key.

4.4 Strategic management of traceability

The PAViX offers full operation traceability. General traceability options can be configured from the home page of the PAViX HMI. Press the “TRACK” button to access.




Figure 19: Access to traceability options management

Traceability is based on a bar code or QR code system.

User traceability (USER) is guaranteed for a maximum of 20 characters, its activation being specific to the staking-tool.

MO traceability is guaranteed for numbers containing up to 20 characters, its activation being specific to the staking-tool.

Traceability by movement serial numbers is guaranteed for numbers containing up to 10 characters. Activation of serial number traceability is done in the programs via the “TRACK ID” radio button on the program’s main page.

Unique or continuous ID:

If « TRACK ID » is activated in the program, it is possible to set a continuous or unique traceability :

- Unique : the ID is requested on each movement (for example: useful for movement traceability)
- Continuous : the ID is kept in memory until a new one is scanned (for example: useful for needle supplier traceability)
-

These settings are automatically transferred to PAViX staking-tools when updating the hand-setting programs.

Note: These options may be temporarily changed in the staking-tool’s “Traceability” menu.

4.5 Program import / export

When programs are updated/developed, they may be transferred on a SD card using the SD reader located on the left-hand side of the HMI.

Similarly, programs contained on the SD card may be transferred to an HMI. This operation is carried out using the Import/Export buttons located in the left column in the program management page.




Figure 20: Import and export commands in the navigation pane

4.5.1 Exporting

After having pressed the “Export” button on the “Program Management” page, confirmation of export is requested.




Figure 21: Exporting

Exporting program-related bar codes is optional.



Figure 22: Export, question

NOTE (1): barrel configuration is always exported to the external SD card.

NOTE (2): non-initialised programs (listed in red on the “Program Management” page) are not exported.

NOTE (3): any program potentially present of the SD card is deleted. The HIM programs are then exported.

4.5.2 Importing

Below, the program import procedure from the external SD card.
The families and programs that do not exist in the HIM are created.




Figure 23: Importing

If a program already exists in the HMI, the operator is required to reply to the question below:



Figure 24: Import, question

By clicking on “Yes”, the program present on the SD card replaces the one present on the HMI. The operator can specify whether he wishes to perform the action (“Yes” or “No”) for all future cases which may arise.

NOTE: When importing, the barrel configuration is always imported from the external SD card.

 **The SD cards used must be formatted to FAT32, allocation unit size 1024 for full formatting.**

4.6 Software update

If a software update is available, the administrator will receive an e-mail from VOH SA containing a ZIP file called "PAViX_HMI_vx_xx". In order to update the HMI, open the ZIP file containing a folder called "BL". Move this folder to an empty SD card then insert this SD card to the HMI (turned off). The update starts when the HMI is turned on.







Figure 25: HMI software update

Caution: Do not turn off or remove the SD card during the update!

Once the update is complete, the HMI automatically displays the home screen.

Caution: After the update is successfully completed, restart the HMI.

Various error screens may be displayed:

PAViX screen	Comment(s)
No application in flash memory! 	The HMI is not programmed, please insert a SD card with the corresponding BL folder.
Don't remove SD card! 	The SD card was removed during the programming process. Replace the card in its holder.
Program not valid! 	The program contained on the SD card is not valid. Copy the appropriate program to the SD card.

NOTE (1): If the SD card contains the same version as the one already present on the HMI, no message shall be displayed and the HMI will start normally.

5 PAViX - staking-tool

The PAViX is equipped with all the technology required to master the setting of hands. It has an adjustable stop driven by a motor, a force sensor and a cleat selection system.




Figure 26: PAViX

5.1 Cleat loading / changing

The PAViX is equipped with a barrel that can accommodate up to 7 cleats.



Figure 27: Cleat properly positioned in the barrel, position no. 1 / cleat

NOTE: Be careful not to soil the end of the cleats when handling them so as to avoid transferring dirt to set hands.

5.2 Battery change and recharging

The PAViX is powered by a battery accessible from the back of the staking-tool. It may be removed using the opening located under the device. Batteries are charged in a dedicated charger.



Figure 28: Battery and charger / Changing the battery

5.3 Battery change (CR2032)

The PAViX is equipped with a sensor that measures the height of the stop. This sensor is powered by a CR2032 battery located at the back of the staking-tool. To change this battery, simply remove its holder by unscrewing both its retainer screws.



Figure 29: CR2032 battery holder

NOTE: After having replaced the battery, recording the spindle reference again is required, as per the procedure set out in § 5.6.4 Spindle reference, page 23.

Note: The lifespan of a CR2032 battery is of approximately 1 year.

5.4 PAViX LCD

The PAViX is equipped with a LCD screen where information relating to ongoing operations is displayed. The screen's different sections are used as follows:













Figure 30: PAViX LCD information sections













There are two types of buttons for the left and right sections: simple or double buttons. The bar located under the button's icon means the length of pressure required to perform the function: a short impulse for the short bar, a 1.5 second pressure for the long bar:



Figure 31: Simple button (right) and double button (left). To enable the “PAViX settings” function, press and hold down the button

The following buttons and icons are used on the PAViX display

Buttons	Description
	Validation
	Back to the previous page
	ON / OFF
	“Guest” identification
	“Expert” identification
	Manual program selection
	Height change
	Back to the previous operation Exit the program
	Back Edition of part-holder reference

Icons	Description
	Barrel selection
	PAViX settings
	Height
	Height difference
	Bluetooth
	Battery
	Program updates
	Traceability DATA export
	PAViX memory eraser
	SD card
	Current operation
	Memory usage (here ¼ still available)

5.5 Start up

Before starting the PAViX, ensure a properly charged battery is in place in the holder located at the rear of the staking-tool.

To start the PAViX, simply press and hold the button located on the right-hand side of the LCD screen.



Figure 32: Starting the PAViX - press and hold the right-hand side button

5.6 Configuration of PAViX settings

PAViX basic settings are accessible through the “settings” icon during startup of the staking-tool.



Figure 33: PAViX - “settings” icon to the left

Navigation in the “settings” menu is done with the barrel.




Figure 34: PAViX configuration menus

The icon located at the bottom centre of the screen represents the barrel function.

5.6.1 Barrel configuration

The system uses a barrel configuration common to all programs. This configuration can be displayed from the barrel configuration menu. Furthermore, when this menu is displayed, the PAViX motorised stop places itself in the upper position so as to facilitate the loading/unloading of cleats.
















Figure 35: Barrel configuration


5.6.2 Recording cleat references

The height of the cleats present in the barrel may vary (replacement or polishing of a cleat). It is therefore necessary to save these heights by teaching.

NOTE: Cleat references cannot be recorded before the spindle reference (refer to § 5.6.4 Spindle reference, page 23).

PAViX screen	Comment(s)	PAViX
	Teaching of cleat heights is done from the cleat references menu	
	Select the barrel position for which a cleat reference is required.	
 	Once selection is made, the staking-tool will move the stop to the low position. Place the standard cleat (PAViX ET) on the plate.	
	Height reference is taken using a given force, which is why the staking-tool tares the force before height reference is performed (please do not touch the tray during this phase).	
	Press the spindle down so the cleat comes into contact with the movement and the light turns green (meaning the force has been reached). When it is green for >2s, the PAViX records the reference.	

<p>Ref in progress</p> 	<p>The user must hold the spindle in position while the reference is being recorded.</p> <p>NOTE: If the force becomes too great or too weak when the reference is being recorded, the process is interrupted.</p>	
  	<p>Once the reference is recorded, the user can release the spindle. A check mark appears under the barrel position for which reference was taken.</p> <p>Repeat the above operations for each cleat.</p> <p>If one barrel position is not used, the display will indicate it as void.</p>	

 It is crucial to perform the operation on all active positions

5.6.3 Time/Date

The PAViX offers extended traceability options. For these to be relevant, it is required to set the time on the PAViX clock. This setting is done from the "Time/Date" menu. The selected field is underlined. To change its value, use the barrel and validate with the right-hand side button.




Figure 36: Setting the time and date











5.6.4 Spindle reference

The PAViX is equipped with an absolute height measuring system. This system is powered by a CR2032 battery located at the back of the staking-tool. When the battery voltage drops below the operational threshold, the PAViX notifies the user for him/her to replace it.



Figure 37: Low battery warning and battery housing for the height measuring function (CR2032)

Once the battery has been replaced, the PAViX requires a height reference record. This height reference must be carried out with the standard spindle. The procedure to apply is as follows.

PAViX screen	Comment(s)	PAViX
	After the CR2032 battery has been replaced, the PAViX cannot be used until the height reference has been recorded	
  	Remove a cleat or place an empty barrel slot under the spindle. Place the standard spindle on the plate (PAViX EB)	
	Manually lower the stop using the wheel and validate when this operation is complete	
	Press the spindle down so the cleat comes into contact with the movement and the light turns green (meaning the force has been reached). When it is green for >2s, the PAViX records the reference.	
	<p>The user must hold the spindle in position while the reference is being recorded.</p> <p>NOTE: If the force becomes too great or too weak when the reference is being recorded, the process is interrupted.</p> <p>Reference recorded.</p>	

5.6.5 User type change

The PAViX manages two types of users: Operator and Locked.

In Operator mode, the user can correct hand fitting heights. In Locked mode, this operation is not possible.




Figure 38: User mode selection

⚠ “Operator” mode is the same as the checked “Ht correction” radio button in the HIM (refer to § 4.2.5 Authorisation to correct hand fitting heights, page 14). A change of user type in the staking-tool overwrites the setting selected when creating the programs in the HMI.

5.6.6 Buzzer

The PAViX provides a sound signal option during operations. These signals are configured from the “Buzzer” menu.




Figure 39: Sound signals on force(a) / on stop(b)

Depending on the selected settings, a sound is released:

- When the min force is reached and when the maximum force is exceeded
- When the maximum force is exceeded
- When the stop is reached

5.6.7 LED

The PAViX also provides the option to indicate the hand fitting status in three different colours: orange if the force is below tolerance, green if the force is within the tolerance range and red if the maximum force is exceeded.

The intensity of these light signals can be configured from the “LED” menu. It is possible to configure the intensity or disable the signal with the barrel.




Figure 40: Light intensity adjustment

5.6.8 Screen contrast

The PAViX provides the option to adjust the screen’s contrast so as to adapt to various light environments.




Figure 41: Screen contrast adjustment

5.6.9 Sleep timer

As the PAViX is self-sufficient in energy, a timer enables the Standby mode when the device is not being used. This timer can be set from the “Sleep timer” menu to: 10 minutes, 30 minutes or Disabled (no automatic activation of the Standby mode).




Figure 42: Setting the time before standby

5.6.10 Bluetooth

The PAViX is equipped with a Bluetooth function. It can be configured so as to be used in different ways:

- Off
- Used with a scanner
- Used with a PC/tablet.




Figure 43: Bluetooth adjustment options

5.6.11 Use of a bar code reader (Bluetooth scanner)

If the user wishes to use a bar code scanner, he/she must first connect it to the PAViX. This operation can be done using the “Scanner” menu.

Before starting the staking-tool, ensure the scanner is in Bluetooth® SPP mode. To this end, start the scanner using the switch located at the back and scan the bar codes below in order (that can also be found on the user guide supplied with the scanner)







Figure 44: Bar code for SPP mode configuration

Once the scanner is in SPP mode, it flashes blue for as long as it is not connected to the staking-tool. The procedure described below can then be performed. Once the scanner is connected and switched on, the staking-tool automatically detects its presence at less than 1m away.

PAViX screen	Comment(s)
	<p>When the “Scanner” menu is selected, the PAViX performs a search of the scanners in its range. The scanners are then classified depending on their distance to the PAViX. NOTE: If no scanner is detected, an error message is displayed.</p>
	<p>The user then selects the scanner’s corresponding MAC address he/she wishes to pair up.</p>
	<p>The PAViX then establishes the connection with the scanner and informs the user on the outcome of the operation (success or not). NOTE: The scanner emits a sound when the connection is established.</p>

The PAViX can only pair with one bar code reader (Item no.: 26.01001.SP.09).



Figure 45: Bluetooth scanner (Item no.: 26.01001.SP.09)

Scanner operation: § 4.3.3 Scanner, page 10.

5.6.12 Information

The Information menu displays all the information relating to the staking-tool:

- Staking-tool SN
- Staking-tool software version
- Force sensor SN

5.6.13 Language

The PAViX provides the option to select the language from the “Language” menu.




Figure 46: Configuration of the PAViX language

5.6.14 Traceability

The PAViX offers extended traceability options. Traceability rules are configured from the “Traceability” menu. Traceability can be enabled on the users (USER), manufacturing orders (MO) and continuous ID traceability by entering the administrator password (1234). Movement serial number traceability is enabled in each program (via the PAViX HMI)




Figure 47: Traceability summary

NOTE: Traceability settings can also be managed from the PAViX HMI (Refer to § 4.4 Strategic management of traceability, page 14).

Note: Continuous ID traceability allows the scanned ID to be stored in the memory when moving to the next movement (Refer to § 6.3.2 Hand-setting, page 37). If this setting is disabled (OFF), a new ID scan is requested after each movement.








5.7 Program and data management

The PAViX “ADMIN” menu allows for the following actions:

- Recovery of hand fitting results
- Program updates

5.7.1 Access to the ADMIN menu




The Administrator mode (ADMIN) is used to update programs, export results of hand-setting operations saved by the staking-tool as well as reset the device’s memory. Resetting the memory erases all hand-setting programs as well as traceability data contained in the device. Access to the Admin mode is done using the following password: 1234

PAViX screen	Comment(s)	PAViX
  	<p>The ADMIN menu is accessible via one of the configuration pages: press and hold the PAViX left-hand side button to enter the setting mode.</p> <p>Then, by rotating the barrel to the left, the ADMIN menu will appear.</p> <p>Confirm access with the right-hand side button.</p>	
  	<p>The barrel allows the user to select the number to display, the right-hand side button is used to confirm the choice.</p>	
	<p>See below for use of the ADMIN mode.</p>	

5.7.2 Program updates

The programs contain the fitting parameters required for hand setting operations.

In order to use the PAViX, it must contain hand-setting programs that are transferred using a SD card according to the following procedure:

PAViX screen	Comment(s)	PAViX
	<p>To transfer programs, insert the SD card and select .</p> <p>NOTE: When updating, the information contained on the SD card has priority</p> <p>When the user validates the action with the right-hand side button, the programs contained in the device's memory are updated and hand fitting data is automatically transferred to the SD card.</p>	




The PAViX memory can contain up to 1,000 programs. The PAViX memory can be erased using the Trash icon from the ADMIN menu. When updating the programs, movement holder height references are erased.


⚠ The SD cards used must be formatted to FAT32, allocation unit size 1024 for full formatting.

5.7.3 Recovery of hand fitting results

The PAViX is equipped with a system that traces hand-setting operations. The PAViX can store up to 9,000 operations.

We therefore recommend saving the device's memory on a regular basis. Data export is carried out as follows:

PAViX screen	Comment(s)	PAViX
	<p>To retrieve stored data, insert the SD card and select ().</p> <p>NOTE: The data stored in the PAViX memory is erased after the transfer.</p>	

<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: auto;"> Exportation  </div>	<p>When the user validates the action with the right-hand side button, the data contained in the device's memory is transferred to the SD card.</p>
---	---

- The results are exported in a ".csv" format that can be opened in an Excel-type spreadsheet.
- Results are sorted by staking-tool and by program
- If a program is already present, data is added at the end of the file

Below is an overview of a PAViX export opened on a Windows PC:




Figure 48: SD on PC and SD tree structure

OF	ID	Réf.	Aiguille	porte-pièce	Hauteur	Cor. Hauteur	H OK/KO	Fmin	Fmax	Force	F OK/KO	Date	User
Machine=PAViX													
SN=07300023													
Famille=Famille1													
Programme=Programme1													
OF-02-EPHJ	556	DEMO_VOH-2	hre	A000A	-0.55	0	OK	10	55	19.8	OK	15.09.2017 17:31	RVA
OF-02-EPHJ	556	DEMO_VOH-2	sec	A000A	-0.55	0	OK	10	50	20.1	OK	15.09.2017 17:31	RVA
OF-02-EPHJ	556	DEMO_VOH-2	min	A000A	-0.55	0	OK	10	55	29.3	OK	15.09.2017 17:31	RVA
OF-02-EPHJ	556	DEMO_VOH-2	HRE	A000A	0.02	0	OK	15	55	30.1	OK	15.09.2017 17:31	RVA
OF-02-EPHJ	556	DEMO_VOH-2	MIN	A000A	0.53	0	OK	15	55	30.4	OK	15.09.2017 17:32	RVA
OF-02-EPHJ	556	DEMO_VOH-2	SEC	A000A	1	0	OK	15	55	28.7	OK	15.09.2017 17:32	RVA
OF-02-EPHJ	519	DEMO_VOH-2	hre	A000A	-0.55	0	OK	10	55	28.9	OK	15.09.2017 17:32	RVA
OF-02-EPHJ	519	DEMO_VOH-2	sec	A000A	-0.55	0	OK	10	50	23.1	OK	15.09.2017 17:32	RVA
OF-02-EPHJ	519	DEMO_VOH-2	min	A000A	-0.55	0	OK	10	55	28.5	OK	15.09.2017 17:32	RVA
OF-02-EPHJ	519	DEMO_VOH-2	min	A000A	-0.55	0	OK	10	55	22.6	OK	15.09.2017 17:33	RVA
OF-02-EPHJ	519	DEMO_VOH-2	HRE	A000A	0.02	0	OK	15	55	22.2	OK	15.09.2017 17:33	RVA
OF-02-EPHJ	519	DEMO_VOH-2	MIN	A000A	0.53	0	OK	15	55	26.9	OK	15.09.2017 17:33	RVA
OF-02-EPHJ	519	DEMO_VOH-2	SEC	A000A	1	0	OK	15	55	31.8	OK	15.09.2017 17:33	RVA
DEMO_VOH-1	1	DEMO_VOH-2	hre	A000A	-0.55	0	OK	10	55	14.6	OK	15.09.2017 17:42	DV
DEMO_VOH-1	1	DEMO_VOH-2	sec	A000A	-0.55	0	OK	10	50	19.9	OK	15.09.2017 17:42	DV
DEMO_VOH-1	1	DEMO_VOH-2	min	A000A	-0.55	0	OK	10	55	23.5	OK	15.09.2017 17:42	DV
DEMO_VOH-1	1	DEMO_VOH-2	HRE	A000A	0.02	0	OK	15	55	23.7	OK	15.09.2017 17:42	DV
DEMO_VOH-1	1	DEMO_VOH-2	MIN	A000A	0.53	0	OK	15	55	22.2	OK	15.09.2017 17:42	DV
DEMO_VOH-1	1	DEMO_VOH-2	SEC	A000A	1	0	OK	15	55	26.7	OK	15.09.2017 17:42	DV
DEMO_VOH-1	A001A	DEMO_VOH-2	hre	MAN	-0.55	0	OK	10	55	22.7	OK	15.09.2017 17:43	DV
DEMO_VOH-1	A001A	DEMO_VOH-2	sec	MAN	-0.55	0	OK	10	50	19.5	OK	15.09.2017 17:43	DV
DEMO_VOH-1	A001A	DEMO_VOH-2	min	MAN	-0.55	0	OK	10	55	23.2	OK	15.09.2017 17:43	DV
DEMO_VOH-1	A001A	DEMO_VOH-2	HRE	MAN	0.02	0	OK	15	55	24	OK	15.09.2017 17:43	DV
DEMO_VOH-1	A001A	DEMO_VOH-2	MIN	MAN	0.53	0	OK	15	55	21.2	OK	15.09.2017 17:43	DV
DEMO_VOH-1	A001A	DEMO_VOH-2	SEC	MAN	1	0	OK	15	55	22.3	OK	15.09.2017 17:43	DV

Figure 49: Example of a .csv file content exported from the PAViX

5.8 Software update

If an update is available, the administrator will receive an e-mail from VOH SA containing a ZIP file called "PAViX_potence_vx_xx". In order to update the staking-tool, open the ZIP file containing a folder called "BL". Move this folder to an empty SD card then insert this SD card to the staking-tool (turned off). The update starts when the staking-tool is turned on.









Figure 50: Staking-tool software version

⚠ Do not turn off or remove the SD card during programming!

Once the update complete, the PAViX automatically displays the home screen.

Various error screens may be displayed:

PAViX screen	Comment(s)	PAViX
	The staking-tool is not programmed, please insert a SD card with the corresponding BL folder	
	The SD card was removed during the programming process. Replace the card in its holder.	
	The battery is not sufficient to program the staking-tool. Replace the battery	
	The program contained on the SD card is not valid. Copy the appropriate program to the SD card.	

6 Hand-setting




In order to have all the information required for traceability purposes, the user may be required to scan a certain number of information before starting hand-setting operations.


6.1 User identification

When starting the PAViX, the user is prompted to identify from the home screen. Identification is carried out with the bar code scanner.



Figure 51: Home screen without a scanner then in User or Expert mode with a connected scanner

The graph located above the “ON/OFF” icon () represents the memory used by the traceability data. The graph is divided into 8 sections. Each section therefore equates to 12.5% of the total memory. When traceability data occupies less than 12.5% of the total memory, the graph is empty (). When the staking-tool is used and the traceability data is stored, the graph gradually fills out. When the memory is full (), the oldest data is replaced by the newest data.

NOTE: Users can identify themselves as guests using the right-hand side button (). In this case, user traceability will be replaced by “GUEST”.





6.2 Selection of the hand-setting program

Starting a hand-setting program can be done two different ways.

- Manual selection
- Automatic selection by bar code (when the scanner is connected)

6.2.1 Manual selection


When manually selecting the corresponding program, the user uses the barrel and the buttons to perform the selection.

PAViX screen	Comment(s)
	After identifying himself/herself, the user presses the right-hand side button () to enable the manual selection of a program.
	The family is then selected using the barrel and validated with the right-hand side button. The left-hand side button takes you back to the previous page.
	The program is then selected using the same method.

6.2.2 Automatic loading of the bar code program

For automatic selection by bar code, the user uses the bar code scanner to select a program.

The link between a bar code and a program is done in the PAViX HMI (Refer to § 4.3 Management of the bar code database, page 10).

PAViX screen	Comment(s)
	<p>After identifying himself/herself, the user scans a bar code corresponding to the program he/she wishes to call.</p> <p>NOTE: The bar code can contain up to 20 characters maximum.</p>







NOTE: If the bar code read by the scanner matches a program, the program is automatically called.

6.3 Performing a hand-setting operation

When the program is selected (via a scanned bar code or a manual selection from the list of programs), the system needs to know the movement holder height before starting a hand-setting program.





The system will request taking of this "0" reference each time a program starts or will offer to scan a bar code present on the movement holder.

6.3.1.1 Taking a reference without an active scanner

PAViX screen	Comment(s)
	<p>When the program has started and no scanner is active, the user is invited to use the 0 reference.</p> <p>Start by placing the part-holder, then validate with the button located on the right-hand side of the staking-tool.</p>
 	<p>Select the requested barrel position, here no.1.</p> <p>Confirm selection with the right-hand side button</p>
  	<p>The system automatically tares the force once placement of the movement holder is validated.</p> <p>Press the spindle down so the cleat comes into contact with the movement and the light turns green (meaning the force has been reached). When it is green for >2s, the PAViX records the reference.</p>

6.3.1.2 Taking movement holder reference with the scanner

Using the bar code reader streamlines taking of reference 0. The PAViX provides the option to store the heights of the part-holder so as to avoid recording this reference when starting the program. To do this, the part-holders must have bar codes. Starting a program is then done as follows.

PAViX screen	Comment(s)
	<p>Once the program is started, the user is prompted to:</p> <ol style="list-style-type: none"> 1) Record the reference in accordance with standard procedure (Refer to 6.3.1.1, page 35) 2) Scan a part-holder bar code <p>NOTE: If the bar code is known, the PAViX places itself directly in Hand-setting mode.</p> <p>By pressing and holding the left-hand side button, it is possible to change the height of a part-holder whose bar code is already known. Once the button is pressed down, simply follow the information on the screen.</p>
	<p>If the bar code of the scanned part-holder is not known, the user is prompted to create a new part-holder. To do this, simply press the right-hand side button.</p>
	<p>The PAViX then guides the user through the standard reference recording procedure</p>
	<p>Once the reference is recorded, simply validate for the part-holder to be stored and for the program to start</p>

NOTE: Part-holder bar codes must contain 5 characters (alphanumeric).

6.3.2 Hand-setting

When selecting a program, if the staking-tool is not connected to a scanner, the user is prompted to record the working reference in accordance with the procedure presented in Paragraph 4.2.2 , page 35. Once the reference is recorded, the hand-setting program can start.




Figure 52: Hand-setting screen




Figure 53: Hand-setting screen (barrel position turns black when it matches the one defined in the program)




Figure 54: Hand fitting result screen

When the user selects an active cleft (by turning the barrel), the PAViX automatically adjusts the stop height as well as the information displayed on the screen. During the adjustment of the height, the luminous surface flashes blue.




Figure 55: Flashing luminous surface during height adjustment and other automatic operations

The user performs the hand fitting operation by lowering the spindle that, when passing through the barrel, takes the selected cleft. During the operation, light and sound signals indicate the change in force.












Figure 56: Force change indication during the hand-setting operation

The operator is guided by the PAViX during the hand-setting operations, as shown in the diagram below.

PAViX screen	Comment(s)
	If ID traceability is enabled and a scanner is connected, the PAViX prompts the operator to enter a movement identification bar code.
	At the start of the program, the PAViX prompts the operator to select the required barrel position (position 7)
	Once the position is selected, the number 7 goes to a black box and the staking-tool moves to the appropriate height. The operator can then place the hand
	When the hand fitting operation is complete, its result is displayed. Of everything is OK, the result is automatically validated after 3 seconds and the following instruction is displayed.
	In the event of a KO, the operator will need to validate the operation with the right-hand side button, then a simple short impulse on the left-hand side button will repeat the operation with a compliant hand.
	The PAViX then prompts the operator to move to barrel position no.1 in order to mount the next hand
	Once the position is selected, the number 1 goes to a black box and so forth until the end of the program
	After the last hand fitting operation (barrel position no.3 in the program opposite), the operator may move to the next movement (right-hand side button) or start a new MO by exiting the program (left-hand side button)

6.3.3 Hand-setting operation results

The PAViX is used to carry out hand-setting operations on an industrial scale. Productivity is critical while maintaining operation traceability and control.

The result of a hand-setting operation is determined based on the force applied to the hand when the spindle comes into contact with the stop. The force saved for traceability purposes is the force measured at the moment the stop comes into contact with the spindle.




Figure 57: Indication of the result (force at stop contact within the tolerance range, without exceeding the max. tolerance)

The following situations may also occur:




Figure 58: KO operation ($F > \text{max. tol}$)

If, during the operation, the max. tolerance is exceeded, the operator is supposed to stop what he/she is doing. The result of the operation is then KO ($F > \text{max. tol}$ and stop not reached). The light signal is fixed red. If the operator continues to the stop, the result will be considered KO and the force saved for traceability purposes shall be the maximum force observed during the operation.




Figure 59: KO operation ($F < \text{min. tol}$)

If the force measured when the stop contact is detected is below the min tolerance, the result will be considered KO. The force saved for traceability purposes is the force measured at the moment the stop comes into contact with the spindle.

In order to manage cases very close to the upper limit, the PAViX is equipped with an intelligent system that takes into account human reaction time (0.1s). If the measured force exceeds the max tolerance by less than 10% in a time interval smaller than 0.1s before stop detection, the operation is considered successful. Furthermore, as the displacement potentially applied during the 0.1s is low, the movement will not be damaged. The force saved for traceability purposes is the force measured at the moment the stop comes into contact with the spindle.




Figure 60: Smart detection, OK operation and details

The results for the setting operation are indicated as soon as the stop is reached or the max force is exceeded.

	$F < F_{min}$	$F_{min} < F \leq F_{max}$	$F > F_{max}$
Stop reached	KO F 12N KO ⚙️ OK <input checked="" type="checkbox"/>	OK F 34N OK ⚙️ OK <input checked="" type="checkbox"/>	KO F 75N OK ⚙️ OK <input checked="" type="checkbox"/>
Stop not reached	N/A	N/A	KO F 65N KO ⚙️ KO <input checked="" type="checkbox"/>

The results in red must be acknowledged by the operator using the right-hand side button. OK operations are automatically validated after a period of 1.5 seconds.

6.3.4 Height corrections

If the "Ht correction" option has been enabled in the HMI when creating the programs or when the "Operator" mode is selected in the staking-tool, it is possible to correct hand fitting heights by pressing and holding the right-hand side button (as long as the current barrel position matches the current operation):




Figure 61: Hand fitting in "Operator" mode (equivalent of the "Ht correction" option of the HMI)

When the button has been pressed and held down, the following page is displayed:




Figure 62: Height correction page

Simply turn the height setting wheel to perform the correction. The correction is displayed on the screen in mm.

Note: Height correction is available in this program on a temporary basis. It is lost when the user leaves the program.

7 Exclusion of liability/guarantee

Damages caused by conditions of use, transport or storage non-compliant with the conditions described in this manual are not supported by the manufacturer. Changes to the device and opening of the casing are forbidden and lead to exclusion of liability. Guarantee rights expire when it is proven that the detected faults are not from origin.

8 Maintenance and service

8.1 Cleaning of the spindle

Frequency: Once a week (depending on use)

Equipment required:

- Light Benzine
- Clean cloth

Stage	Description
1	Remove the spindle
2	Dampen the cloth with light Benzine
3	Clean the entire length of the spindle
4	Let the spindle dry before putting back into place

8.2 Cleaning of spindle smooth bearings

Frequency: Once a week (depending on use)

Equipment required:

- Light Benzine
- Cotton buds

Stage	Description
1	Remove the spindle
2	Dampen a cotton bud
3	Clean the upper bearing
4	Clean the lower bearing
5	Let the spindle dry before putting back into place

8.3 Replacement of the backup battery (CR2032)

Frequency: Once a year (depending on the staking-tool's signals)

Equipment required:

- CR2032 battery
- Watchmaker's screwdriver - 140
- Spindle height standard










Stage	Description
1	Turn the staking-tool off
2	Remove the main battery
3	Unscrew the two retaining screws of the CR2032 holder
4	Remove the battery holder
5	Replace the used battery with a new one
6	Insert the battery holder in its housing et secure using the screws provided for this purpose
7	Set staking-tool time as described in the user guider
8	Record a spindle reference as per the user guide

8.4 Sensor inspection

8.4.1 Access to the Maintenance menu

The Maintenance mode is used to inspect distance and force sensors.

This is done by validating the force or distance measurement by using a weight or a gauge block. Access to the Maintenance mode is done using the following password: **7426**

PAViX screen	Comment(s)	PAViX
  	<p>The Maintenance menu is accessible via one of the configuration pages: press and hold the PAViX left-hand side button to enter the Setting mode.</p> <p>Then, by rotating the barrel twice to the left, the Maintenance menu will appear.</p> <p>Confirm access using the right-hand side button.</p>	
  	<p>The barrel allows the user to select the number to display, the right-hand side button is used to confirm the choice.</p>	
  	<p>The barrel is used to select the validation to perform:</p> <ul style="list-style-type: none"> - Distance : "Position[um]" - Force: "Valid[N]" 	















8.4.2 Verifying force measurement accuracy

Verification of force measurement accuracy requires a quiet environment as well as a rigid and stable work surface.

Equipment required:


- Force measurement accuracy verification kit VOH 26.01001.SP11
- Standard spindle VOH 26.01001.SP04

Fitting procedure

PAViX screen	Comment(s)	PAViX
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center;">Valid[N]</p> <p style="text-align: center;">    </p> </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center;">Initialisation...</p> <p style="text-align: center;">  </p> </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center;">Remove the spindle</p> <p style="text-align: center;">  1/11  </p> </div> <div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">Remove cleat</p> <p style="text-align: center;">  2/11  </p> </div>	<p>Remove the spindle and cleat in position under the spindle.</p> <p>To facilitate cleat removal, the spindle automatically moves to a high position during initialisation.</p>	
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> <p style="text-align: center;">Place spindle gauge block</p> <p style="text-align: center;">  3/11  </p> </div> <div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">Place the plate of calibration</p> <p style="text-align: center;">  4/11  </p> </div>	<p>Start by placing the standard spindle (SP.04 "EB") on the plate. Confirm with the right-hand side button.</p> <p>Then place the calibration plate in place of the spindle, resting on the standard spindle. Validate using the right-hand side button</p>	
<div style="border: 1px solid black; padding: 5px;"> <p style="text-align: center;">Force tare...</p> <p style="text-align: center;">  5/11 </p> </div>	<p>The PAViX automatically tares the force: do not touch the calibration plate of the PAViX plate.</p>	

Tare done!		
------------	--	--

Validation procedure:

PAViX screen	Comment(s)	PAViX
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Place on the plate 1kg 6/11 <input checked="" type="checkbox"/> </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Weight: 1.0kg on the plate 9.7[N] <input checked="" type="checkbox"/> ← 7/11 <input checked="" type="checkbox"/> </div> <p style="text-align: center;">■ ■ ■</p> <div style="border: 1px solid black; padding: 5px;"> Weight: 5.0kg on the plate 49.0[N] <input checked="" type="checkbox"/> ← 11/11 <input checked="" type="checkbox"/> </div>	<ol style="list-style-type: none"> 1) Delicately place the required mass on the plate. Confirm placement using the right-hand side button. 2) Once the measurement is stable, confirm using the right-hand side button. <p>These 2 operations must be performed with 1, 2 and 5kg masses.</p>	
<div style="border: 1px solid black; padding: 5px;"> Control results OK under specifications <input checked="" type="checkbox"/> </div>	<p>If the measures are correct, the screen displays "OK".</p>	
<div style="border: 1px solid black; padding: 5px;"> Control results Calibration necessary <input checked="" type="checkbox"/> </div>	<p>Upon the first measure with an out-of-machine-tolerance value, the operator is invited to recalibrate the force. (Refer to § 8.4.3 Force calibration, page 46)</p>	










8.4.3 Force calibration

Force calibration requires a quiet environment as well as a rigid and stable work surface.

Equipment required:

- Calibration plate VOH 26.01003.SP49
- Set of standard weights for calibration VOH 26.01003.SP50
- Standard spindle VOH 26.01001.SP04

Validation procedure:










PAViX screen	Comment(s)	PAViX
	<p>If force validation gives an out-of-machine-specification result, you are prompted to calibrate the force measurement system.</p>	
  	<p>Remove the spindle and cleat in position under the spindle.</p> <p>Then place the calibration plate in place of the spindle, resting on the standard spindle. Confirm with the right-hand side button.</p> <p>Once the measure is stable, the "check mark" button appears. It allows the operator to move to the next step.</p>	<p>Like on the image below, with no weight.</p>
 	<p>Repeat the operations opposite for 1, 2, 5 and 10kg masses.</p>	
	<p>Once calibration is complete, the error relating to the extent of measurement is displayed (≤ 2.0).</p>	
	<p>If the error on the extent of measurement is >2.0, it is not possible to save the calibration.</p> <p>3 consecutive calibrations can be carried out with a result >2.0; after which, VOH SA must be contacted.</p>	

8.4.4 Distance validation

Equipment required:

- Position accuracy verification kit VOH 26.01001.SP.10

Fitting procedure

PAViX screen	Comment(s)	PAViX
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Position[um]  </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Initialisation...  </div> <div style="border: 1px solid black; padding: 5px;"> Remove cleat  </div>	Remove the cleat in position under the spindle.	
<div style="border: 1px solid black; padding: 5px;"> Place 2 20mm wedges on the plate  </div>	Place two 20mm wedges next to one another on the plate	
<div style="border: 1px solid black; padding: 5px;"> Place the 4.5mm wedge on the plate  </div>	On top, in the centre of the plate and perpendicularly: a 4.5mm wedge	
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Force tare... in progress...  </div> <div style="border: 1px solid black; padding: 5px;"> Push on spindle until green LED  </div>	<p>Follow staking-tool instructions, identical to that of taking a spindle reference. (Apply minimum force and wait for contact with the stop)</p> <p>Repeat the height reference taking operation for a 10mm wedge, as subsequently specified by the staking-tool.</p>	

<div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p>Measure n°1 done</p> <p>5/9 <input checked="" type="checkbox"/></p> </div>		
<div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p>Control results OK under specifications</p> <p>9/9 <input checked="" type="checkbox"/></p> </div>	<p>If the measures are correct, the screen displays "OK".</p>	
<div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p>Control results Bracket error Please contact VOH SA</p> <p>9/9 <input checked="" type="checkbox"/></p> </div>	<p>When the measures do not meet machine specifications, please contact VOH SA.</p>	

9 Representation/distribution

